





36. 17th floor, adjacent to room S1704A - Close-up of delaminated fireproofing debris on top of suspended ceiling




37. 17th floor, elevator lounge area - General view of partition wall located beneath acoustical spray ceiling




38. 17th floor, elevator lounge area - General view of accoustical spray ceiling above elevators





39. 17th floor, elevator lounge area - Close-up of hole in acoustical sprayed ceiling



40. 17th floor, elevator lounge area - Location of dust sample #4